C.L. "BUTCH" OTTER – Governor RICHARD M. ARMSTRONG – Director TAMARA PRISOCK—ADMINISTRATOR
DIVISION OF LICENSING & CERTIFICATION
DEBRA RANSOM, R.N.,R.H.I.T., Chief
BUREAU OF FACILITY STANDARDS
3232 Elder Street
P.O. Box 83720-0009
Boise, ID 83720-0009
PHONE 208-334-6626
FAX 208-364-1888

May 19, 2017

James Elton, Administrator Wellspring Health & Rehabilitation of Cascadia 2105 12th Avenue Road Nampa, ID 83686-6312

Provider #: 135094

RE: FACILITY FIRE SAFETY & CONSTRUCTION SURVEY REPORT COVER LETTER

Dear Mr. Elton:

On May 10, 2017, a Facility Fire Safety and Construction survey was conducted at Wellspring Health & Rehabilitation of Cascadia by the Department of Health & Welfare, Bureau of Facility Standards to determine if your facility was in compliance with State Licensure and Federal participation requirements for nursing homes participating in the Medicare and/or Medicaid programs. This survey found that your facility was not in substantial compliance with Medicare and Medicaid program participation requirements. This survey found the most serious deficiency to be a widespread deficiency that constitutes no actual harm with potential for more than minimal harm that is not immediate jeopardy, as documented on the enclosed CMS-2567, whereby significant corrections are required.

Enclosed is a Statement of Deficiencies and Plan of Correction, Form CMS-2567, listing Medicare and/or Medicaid deficiencies. If applicable, a similar State Form will be provided listing licensure health deficiencies. In the spaces provided on the right side of each sheet, answer each deficiency and state the date when each will be completed. Please provide ONLY ONE completion date for each federal and state tag in column (X5) Completion Date to signify when

James Elton, Administrator May 19, 2017 Page 2 of 4

you allege that each tag will be back in compliance. **NOTE**: The alleged compliance date must be after the "Date Survey Completed" (located in field X3) and on or before the "Opportunity to Correct" (listed on page 2). After each deficiency has been answered and dated, the administrator should sign the Statement of Deficiencies and Plan of Correction, CMS-2567 Form in the spaces provided and return the originals to this office. If a State Form with deficiencies was issued, it should be signed, dated and returned along with the CMS-2567 Form.

Your Plan of Correction (PoC) for the deficiencies must be submitted by May 31, 2017. Failure to submit an acceptable PoC by May 31, 2017, may result in the imposition of civil monetary penalties by June 20, 2017.

Your PoC must contain the following:

- What corrective action(s) will be accomplished for those residents found to have been affected by the deficient practice;
- How you will identify other residents having the potential to be affected by the same deficient practice and what corrective action(s) will be taken;
- What measures will be put into place or what systemic changes you will make to ensure that the deficient practice does not recur;
- How the corrective action(s) will be monitored to ensure the deficient practice will not recur, i.e., what quality assurance program will be put into place; and,
- Include dates when corrective action will be completed.
- The administrator must sign and date the first page of both the federal survey report, Form CMS-2567. If a State Form was issued as well, it should also be signed, dated and returned.

All references to federal regulatory requirements contained in this letter are found in Title 42, Code of Federal Regulations.

Remedies will be recommended for imposition by the Centers for Medicare and Medicaid Services (CMS) if your facility has failed to achieve substantial compliance by **June 14, 2017**, (Opportunity to Correct). Informal dispute resolution of the cited deficiencies will not delay the imposition of the enforcement actions recommended (or revised, as appropriate) on **June 14, 2017**. A change in the seriousness of the deficiencies on **June 14, 2017**, may result in a change in the remedy.

James Elton, Administrator May 19, 2017 Page 3 of 4

The remedy, which will be recommended if substantial compliance has not been achieved by **June 14, 2017**, includes the following:

Denial of payment for new admissions effective **August 10, 2017**. 42 CFR §488.417(a)

If you do not achieve substantial compliance within three (3) months after the last day of the survey identifying noncompliance, the CMS Regional Office and/or State Medicaid Agency must deny payments for new admissions.

We must recommend to the CMS Regional Office and/or State Medicaid Agency that your provider agreement be terminated on **November 10, 2017**, if substantial compliance is not achieved by that time.

Please note that this notice does not constitute formal notice of imposition of alternative remedies or termination of your provider agreement. Should the Centers for Medicare & Medicaid Services determine that termination or any other remedy is warranted, it will provide you with a separate formal notification of that determination.

If you believe these deficiencies have been corrected, you may contact Nate Elkins, Supervisor, Facility Fire Safety and Construction, Bureau of Facility Standards, 3232 Elder Street, PO Box 83720, Boise, ID 83720-0009, Phone #: (208) 334-6626, option 3; Fax #: (208) 364-1888, with your written credible allegation of compliance. If you choose and so indicate, the PoC may constitute your allegation of compliance. We may accept the written allegation of compliance and presume compliance until substantiated by a revisit or other means. In such a case, neither the CMS Regional Office nor the State Medicaid Agency will impose the previously recommended remedy, if appropriate.

If, upon the subsequent revisit, your facility has not achieved substantial compliance, we will recommend that the remedies previously mentioned in this letter be imposed by the CMS Regional Office or the State Medicaid Agency beginning on May 10, 2017, and continue until substantial compliance is achieved. Additionally, the CMS Regional Office or State Medicaid Agency may impose a revised remedy(ies), based on changes in the seriousness of the non-compliance at the time of the revisit, if appropriate.

In accordance with 42 CFR §488.331, you have one opportunity to question cited deficiencies through an informal dispute resolution process. To be given such an opportunity, you are required to send your written request and all required information as directed in Informational Letter #2001-10. Informational Letter #2001-10 can also be found on the Internet at:

James Elton, Administrator May 19, 2017 Page 4 of 4

http://healthandwelfare.idaho.gov/Providers/ProvidersFacilities/StateFederalPrograms/NursingFacilities/tabid/434/Default.aspx

Go to the middle of the page to Information Letters section and click on State and select the following:

BFS Letters (06/30/11)

2001-10 Long Term Care Informal Dispute Resolution Process 2001-10 IDR Request Form

This request must be received by May 31, 2017. If your request for informal dispute resolution is received after May 31, 2017, the request will not be granted. An incomplete informal dispute resolution process will not delay the effective date of any enforcement action.

Thank you for the courtesies extended to us during the survey. If you have any questions, please contact us at (208) 334-6626, option 3.

Sincerely,

Nate Elkins, Supervisor

Facility Fire Safety and Construction

NE/lj

Enclosures

PRINTED: 06/18/2017 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER-	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - ENTIRE BUILDING			(X3) DATE SURVEY COMPLETED	
	135094	B. WING	<b>************************************</b>		08/10/2017	
NAME OF PROVIDER OR SUPPLIER WELLSPRING HEALTH & REM		A. married and the second	210	Reet Address, City, State, Zip Code 15 12th Avenue Road MPA, ID 83688	30710/2017	
PREFIX (EACH DEFICIENC)	TEMENT OF DEFICIENCIES MUST BE PRECEDED BY FULL SC (DENTIFYING INFORMATION)	PREFIX TAG	× :	Provider's plan of correction (EACH corrective action shoul) cross-referenced to the approp deficiency)	DBE COMPLÉTICA	
: K 000 INITIAL COMMEN	rs .	Κo	00			
built in 1998 with at 2001. The facility is smoke detection of	gle story Type V (III) structure addition of 60 beds in March sprinklered throughout with verage in corridors, sleeping paces. The facility is currently IF/NF beds.	; ;	•		•	
annual fire/life safe - 10, 2017. The fac LIFE SAFETY COD	encies were cited during the ty survey conducted on May 9 lity was surveyed under the E, 2012 Edition, Existing ancy, in accordance with 42		;	D	7	
. The Survey was co	nducted by:			CACHITY 3 Cal		
ss=F (ABHR)  · Alcohol Based Han	& Construction Based Hand Rub Dispenser  Rub Dispenser (ABHR)	: . Кз	25	325- Alcohol Based Hand Rub I Maintenance Director and Hou Director were educated on NFI testing ABHR upon dispenser re	se Keeping PA 325 on	
unless all condition  * Corridor is at leas  * Maximum individu gailons (0.53 gallor ounces of Level 1 a  * Dispensers shall i horizontal spacing  * Not more than an	t 6 feet wide al dispenser capacity is 0.32 is in suites) of fluid and 18 ierosols have a minimum of 4-foot eggregate of 10 gallons of		,	House Keeping Director educate process to test hand sanitizers and document completion. The be numbered and logged for earth May 17, 2017	ed staff on upon refili units will	
fluid or 136 ounces aerosol are used in a single smoke compartment outside a storage cabinet, excluding one individual dispenser per room * Storage in a single smoke compartment greater than 6 gallons compiles with NFPA 30			•	Quarterly QA meeting to review Documentation Quarterly for coof ABHR unit testing.		
LABORATORY DIRECTOR'S OR PROVIE	ERISUPPHER EPRESENTATIVE'S SIG	YATURE	<del></del>	TITLE	(X8) DATE	

Any deficiency statement ending with an extensit (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the inclings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the days these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

FORM CMS-2567(02:99) Previous Versions Obsolats

Event ID NG0821 Facility ID MD8001280 If continuation

If continuation sheet Page 1 of 13

	IT OF DEFICIENCIES OF CORRECTION	(Xt) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A SUILDING 01 - ENTIRE BUILDING			(XS) DATE SURVEY COMPLETED	
		135094	B. WING		·	0.5	3/10/2017
•	PROVIDER OR SUPPLIER PRING HEALTH & REF	ABILITATION OF CASCADIA		2105	ET ADDRESS, CITY, STATE, ZIP CODE 12TH AVENUE ROAD 1PA, 1D 83686		7 1 97 22 9 1
(X4) ID PREFIX TAG	EACH DEFICIENCY	TRMENT OF DEFICIENCIES MUST BE PRECEDED BY FULL SO IDENTIFYING INFORMATION)	ID PREF TAG		PROVIDER'S PLAN OF CORRECTIO (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROP DEFICIENCY)	8E	(X5) COMPLETION DATE
K 325	ignition source * Dispensers over of sprinklered smoke (* ABHR does not ex) * Operation of the dispension of the dispens	arpeted floors are in compartments (ceed 95 percent alcohol ispenser shall comply with or 19,3,2,6(11) against inappropriate access 2 CFR Parts 403, 418, 460, anot met as evidenced by: view, observation and a falled to ensure Alcohol ispensers (ABHR) were dance with NFPA 101. Failure the operation of ABHR dance with the manufacturer's choice each time a new reflit is the inadvertently spilling increasing the risk of fires. See affected 59 residents, staff late of the survey. The facility SNF/NF residents and had a day of the survey.	K	325			
	conducted on May 8 9:00 AM to 1:00 PM indicating ABHR dis accordance with mainstructions when a dispensers were obtaind when asked, the facility was not a	facility inspection records  0, 2017 from approximately  1, no records were available  1, pensers were tested in  1, inufacturer's care and use  1, new refill is installed. ABHR  1, served throughout the facility  2, maintenance Director stated  1, ware of the requirement to  1, ors each time a new refill is					

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER.		(X2) MULTIPLE CONSTRUCTION A BUILDING 01 - ENTIRE BUILDING				(X3) DATE SURVEY COMPLETED	
		135094	B WING	Take Manager	ensemble matinisestiming times many are a pleasured screening times and the screening times are a screening times and the screening times are a screening times and the screening times are a screenin	ىم	5/10/2017
	PROVIDER OR SUPPLIE PRING HEALTH & RE	R EHABILITATION OF CASCADIA		2105	EET ADDRESS, CITY, STATE, ZIP CODE 12TH AVENUE ROAD NPA, ID 83686		JILIEVI
(X4) ID PREFIX TAG	(EACH DEFICIENT	TATEMENT OF DEFICIENCIES ICY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	IO PREFIX TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPROPRIES OFFICIENCY)	DSE	COMPLETION DATE
K 325	Continued From p	page 2	K 32	<del>;</del> 25	, , , , , , , , , , , , , , , , , , ,		alle year general year general
	Actual NFPA stand	-					
1	NFPA 101	•	· ·				
;	; Alcohol-based har	Based Hand-Rub Dispensers. nd-rub dispensers shall be dance with 8.7.3.1, unless all of					·
	(1) Where dispens the corridor shall b (1830 mm).	sers are installed in a corridor, have a minimum width of 6 ft					
	capacity shall be a (a) 0.32 gal (1	I.2 L) for dispensers in rooms,					, ·
		as open to corridors (.0 L) for dispensers in suites of					
,	maximum capacity be 18 oz. (0.51 kg	l containers are used, the y of the eerosol dispenser shall ) and shall be limited to Level 1		i.			:
•	aerosols as define Manufacture and :	ed in NFPA30B, Code for the Storage of Aerosol Products.		i			
,	(4) Dispensers sha	all be separated from each I spacing of not less than 48 in					
,	(5) Not more than alcohol-based han	an aggregate 10 gal (37.8 L) of od-rub solution or 1135 oz (32.2 pools, or a combination of		,			Ì
	liquids and Level 1 total, the equivaler (32.2 kg), shall be	1 serosols not to exceed, in nt of 10 gal (37.8 L) or 1135 oz In use outside of a storage		•	-		
;	as otherwise provi (6) One dispenser	smoke compartment, except ided in 19.3.2.8(6). complying with 19.3,2.6 (2) or ocated in that room shall not be					·
,	included in the agg 19.3.2.6(5), (7) Storage of qua	gregated quantity addressed in intities greater than 5 gal (18,9 ke compartment shall meet the					

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1)		(X1) PROVIDER/SUPPLIER/CLIA IDENT/FIGATION NUMBER	(X2) MULTIPLE CONSTRUCTION A BUILDING 01 - ENTIRE BUILDING				(X3) DATE SURVEY COMPLETED	
		135094	B WING		та жиймина и на	l nu	5/10/2017	
	PROVIDER OR SUPPLIE	r EHABILITATION OF CASCADIA		2108	SET AODRESS, CITY, STATE, ZIP CODE 3 12TH AVENUE ROAD 1/PA, ID 83688	1	113018411	
(X4) ID PREFIX TAG	(EACH DEFICIEN	TATEMENT OF DEFICIENCIES CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFI TAG	κ .	PROVIDER'S PLAN OF CORRECTIC (EACH CORRECTIVE ACTION SHOUL) CROSS-REFERENCED TO THE APPROP DEFICIENCY)	DBE	(X5) COMPLETION DATE	
K 325	Continued From p		кз	25				
	requirements of N	IFPA 30, Flammable and	•				,	
	Combustible Liqui	lds Code.		*				
		all not be installed in the			•			
	following locations							
		ignition source within a 1 in. (25					,	
	- mm) nonzontal di - ignition source	stance from each side of the						
		of an ignition source within a 1					,	
		ontal distance from the Ignition						
	Source	and anatomica trail, the Buildi					ļ	
	(c) Beneath a	n ignition source within a 1 in.					:	
	(25 mm) vertical d	listance from the ignition source						
	(9) Dispensers ins	stalled directly over carpeted					İ	
		mitted only in sprinklered						
	smoke compartme							
		pased hand-rub solution shall						
		cent alcohol content by volume.						
	the following criter	the dispenser shall comply with						
		ser shall not release its					•	
		hen the dispenser is activated,						
		automatically by touch-free						
	activetion.	manner, my reason is a						
		tion of the dispenser shall occur						
	only when an obje	ct is placed within 4 in. (100					į	
	mm) of the sensin						ļ	
		placed within the activation zone						
		hall not cause more than one						
	activation.	والمرام والمرام والمرام والمرام والمرام		•	•		j	
		nser shall not dispense more emount required for hand					1	
		t with label instructions.					1	
		rser shall be designed,						
		perated in a manner that					ĺ	
		lental or malicious activation of					j	
	the dispensing de-						į	
	(f) The dispen	ser shall be tested in					ł	
		ne manufacturer's care and use					1	
	instructions each t	ime a new refill is installed.					f	

PRINTED: 05/18/2017 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY AND PLAN OF CORRECTION IDENTIFICATION NUMBER. COMPLETED A BUILDING 01 - ENTIRE BUILDING 135094 B. WING 05/10/2017 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 2105 12TH AVENUE ROAD WELLSPRING HEALTH & REHABILITATION OF CASCADIA NAMPA, ID 83686 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION PREFIX (X5) Completion Date (EACH DEFICIENCY MUST BE PRECEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE PREFIX TAG REGULATORY OR LSC IDENTIFYING INFORMATION) TAG DEFICIENCY) K 331 NFPA 101 Interior Wall and Celling Finish K 331 K331- Interior Wall Finish SSME: Interior Wall and Celling Finish Maintenance Director will spray curtains 2012 EXISTING interior wall and ceiling finishes, including in Theater room, carpet-like wall exposed interior surfaces of buildings such as treatments in main hall, with certified fixed or movable walls, partitions, columns, and Flame retardant June 1, 2017. have a flame spread rating of Class A or Class B. The reduction in class of interior finish for a Maintenance Director will audit facility to sprinkler system as prescribed in 10.2,8.1 is permitted. identity other textiles on walls and 10.2, 19.3.3.1, 19.3.3.2 ceilings requiring treatment and treat Indicate flame spread rating(s). each case individually. This STANDARD is not met as evidenced by: Maintenance Director will document Based on record review, observation and completion of Treatments, and routinely interview, the facility failed to ensure the interior finish limitations were of Class A or Class B. audit facility for like materials, Per Fallure to provide flame spread rating manufacturer guidelines, Maintenance documentation and ensure the flame resistive properties of interior wall finishes could inhibit the Director will repeat treatments annually. spread of fire over the continuous surface. or after deep cleaning of said materials. forming the interior portions of a building. This deficient practice affected 59 residents, staff and visitors on the date of the survey. The facility is licensed for 120 SNF/NF beds and had a census of 59 on the day of the survey, Findings include: ; During review of the facility records conducted on : May 9, 2017 from approximately 9:00 AM to 1:00 . PM, the facility failed to provide documentation of the flame resistive properties of the wall covering in the Theatre room and below the hand rail in the main corridor. Further physical observation revealed the wall covering to be "carpet like". When asked, the Maintenance Director stated the wall covering had been in place since he took his position with the facility and he was not aware of

	OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER.	(X2) MULTIPLE CONSTRUCTION A BUILDING 01 - ENTIRE BUILDING			(X3) DATE SURVEY COMPLETED		
		135094	8 WNG	<b>Electricity</b>		05/10/2017	,	
NAME OF	ROVIDER OR SUPPLIER		- Control of the Cont	STRE	ET ADDRESS, CITY, STATE, ZIP CODE		manupladge	
WELLSP	ring health & ref	ABILITATION OF CASCADIA			112TH AVENUE ROAD 11PA, ID 83886			
(X4) ID PREFIX TAG	(EACH DEFICIENCY	Tement of Deficiencies ' Must be preceded by full sc identifying (NFORMATION)	ID PREFI TAG		Provider's Plan of Correctio (Each Corrective Action Should Cross-Referenced to the Approp Deficiency)	HE COMPLET		
К 331	Continued From pa		, Кз	131				
	its origin or flammai	bility rating.		-				
	Actual NFPA stands	ard:	•					
	NFPA 101			•	•	:		
	19.3.3 Interior Finisi 19.3.3.1 General, In	h, kterior finish shall be in						
•	accordance with Se							
:		all and Textile Ceiling	ı					
		of textile meterials on walls or y with one of the following						
	conditions:	-						
	(1) Textile materials Class A when tested	meeting the requirements of In accordance with ASTM E						
	84, Standard Test N	lethod for Surface Burning						
	Characteristics of 8 or ANSI/UR 723 Sta	uilding Materials, andard for Test for Surface	<b>:</b>					
	Burning Characteris	itics of Building Materials,	,				i	
		preparation and mounting 2404, Standard Practice for	:					
:	Specimen Preparati	on and Mounting of Textile.	•					
		or Ceiling Coverings to ming Characteristics (see						
	10.2.3.4), shall be p	ermitted on the walls or						
	ceilings of rooms or approved automatic	areas protected by an	•			•		
	(2) Textile materials	meeting the requirements of	•					
		I in accordance with ASTM E using the specimen	•				Ì	
:	preparation and mo							
		10.2.3.4), shall be permitted						
		not exceed three-quarters of eight or do not exceed 8 ft						
•	(2440mm)In height,							
•	is less. (3) Textile materials	meeting the requirements of						
•	Class A when tested	I in accordance with ASTM E						
	84 or ANSI/UL 723,	using the specimen	,					

	The state of the s	= & MEDIGAID SERVICES	7		OM BMO	0938-039
	OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	( ' '	IPLE CONSTRUCTION NG 01 - ENTIRE BUILDING	(X3) DAT	E SURVEY IPLETED
		135094	8 WING_	and the state of t	05/	10/2017
	PROVIDER OR SUPPLIER RING HEALTH & RE	HABILITATION OF CASCADIA		STREET ADDRESS, CITY, STATE, ZIP CODE 2106 12TH AVENUE ROAD NAMPA, ID 83686		
(X4) IO PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST SE PRECEDED BY FULL SC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF COR (EACH CORRECTIVE ACTION CROSS-REFERENCED TO THE A DEFICIENCY)	SHOULD BE	(X5) COMPLETION DATE
K 331	Continued From pa	ounting method of	K 33	31;		
,	to extend not more	9 10.2.3.4), shall be permitted than 48 in. (1220 mm) above n ceiling-height walls and tions.	,			
. •	(4) Previously appr textile material med A when tested in ad	oved existing installations of etling the requirements of Class coordance with ASTM E 84 or 10.2.3.4) shall be permitted to		•		•
	and partitions where	used. s shall be permitted on walls re tested in accordance with rd Methods of Fire Tests for				
;	of Textile or Expan Full Height Penels (6) Textile materials	Fire Growth Contribution ded Vinyl Wall Coverings on and Walls. (See 10.2.3.7.) s shall be permitted on walls,			•	
,	accordance with N Fire Tests for Evalu Wall and Celling In	ngs where tested in FPA 286, Standard Methods of lating Contribution of terior Finish to Room Fire		·		
		ა.r.) r System - Maintenance and	K 35	8 K353-Sprinkler System		
SS≔F	Automatic sprinkle	Maintenance and Testing r and standpipe systems are and maintained in accordance		Sprinkler Heads in the Kitc be replaced by certified co specialists June 2, 2017.		
	with NFPA 25, Star Testing, and Mainta Protection Systems	ndard for the Inspection, atning of Water-based Fire s. Records of system design,		The Dry Barrel sprinkler w 2 and serviced to be in cor	mpliance.	n June
	maintained in a sec available.	action and testing are oure location and readily system last checked		Facility sprinklers will all b Maintenance Director to e neither corrosion nor pain	ensure heads i	
	b) Who provided		-	be repeated monthly and Quarterly QA meeting.	reported at th	

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION UDENTIFICATION NUMBER.		(X2) MUI A. BUILD			(X3) DATE SURVEY COMPLETED		
		135094	B WING				5/10/2017
	PROVIDER OR SUPPLIE RING HEALTH & RI	R EHABILITATION OF CASCADIA		210	REET ADDRESS, CITY, STATE, ZIP GODE 16 12TH AVENUE ROAD MPA, ID 83686		
(X4) ID PREFIX TAG	(EACH DEFICIEN	TATEMENT OF DEFICIENCIES CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFI TAG		PROVIDER'S PLAN OF CORRECT (EACH CORRECTIVE ACTION SHOLL DROBS-REFERENCED TO THE APPRO DEFICIENCY)	LD BE	(X5) COMPLETION DATE
	any non-required system. 9.7.5, 9.7.7, 9.7.8 This STANDARD Based on record interview, the facil suppression system free of obstruction Failure to maintain have a detrimental sprinklers by affectinulating thermal or otherwise rend or ineffectual. This	RKS Information on coverage for or partial automatic sprinkler, and NFPA 25 is not met as evidenced by: review, observation and lity falled to ensure fire am pendants were maintained as such as paint or corrosion. In fire sprinkler pendants can all effect on the performance of oling water distribution patterns, elements, delaying operation, ering the sprinkler inoperable a deficient practice affected 59	Кз	.53			
	survey. The facilit	d visitors on the date of the y is licensed for 120 SNF/NF ensus of 59 on the day of the					
	1.) During record approximately 9:0 sprinkler inspection 2016 identified the a.) Obstructed corrosion in the kill b.) The dry be be tested or replain to documentation corrected could be 2.) Further observent	n that the deficiencies had been e produced. ration during the facility tour on n approximately 1;00 PM to 4;30					•
	a.) Eight (8) o	ainted sprinkler heads in the					

STATEMENT OF DEFICIENCIES (X1) PROVIDER/GUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER		1		(X3) DATE SURVEY COMPLETED		
	136094	B. WING		05/10/2017		
			STREET ADDRESS, CITY, STAYE, ZIP CODE 2105 12TH AVENUE ROAD NAMPA, ID 83686	,		
(EACH DEFICIENC	y Must be preceded by Full	PREFIX TAG	(EACH CORRECTIVE ACTION SHOULD	D BE COMPLETION		
Kitchen. b.) One (1) cor walk in refrigerator c.) One (1) cor Laundry. d.) One (1) pai Hallway Shower Ree.) One (1) pai Hallway Soiled Line interview of the Mawas not aware of the survey.  Actual NFPA stand NFPA stand NFPA 25 5.2.1 Sprinklers. 5.2.1.1* Sprinklers. 5.2.1.1.1* Sprinklers floor level annually. 5.2.1.1.1 Sprinklers. 6.2.1.1.2 Any sprint the following shall be fromaterials, paint, and be installed in the cupright, pendent, of the cupright of the	roded sprinkler head in the roded sprinkler head in the 400 pom. Inted sprinkler head in the 500 en Room. Intel sprinkler head in the 500 en Room. Intenance Director revealed he he deficiencles prior to the date ard:  shall be inspected from the ea of corrosion, foreign id physical damage; and shall correct orientation (e.g., r sidewall).  kier that shows signs of any of the replaced:	K 38	the influence the second secon			
(b) Fainting unless manufacturer	heured by the shinkler			:		
	PROVIDER OR SUPPLIER PROVIDER OR SUPPLIER PRING HEALTH & RE SUMMARY ST. (EACH DEFICIENCE REGULATORY OR I  Continued From pa Kitchen, b.) One (1) cor walk in refrigerator c.) One (1) cor Laundry, d.) One (1) pai Hallway Shower Re e.) One (1) pai Hallway Soiled Line Interview of the Ma was not aware of the of the survey.  Actual NFPA stand NFPA 25  5.2.1 Sprinklers.  5.2.1.1* Sprinklers floor level annually.  5.2.1.1.1 Sprinklers floor level annually.  5.2.1.1.2 Any sprin the following shall the (upright, pendent, o  5.2.1.1.2 Any sprin the following shall the (1) Leakage (2) Corrosion (3) Physical damag (4) Loss of fluid in the element (5)*Loading (6) Painting unless	PROVIDER OR SUPPLIER PROVIDER OR SUPPLIER PRING HEALTH & REHABILITATION OF CASCADIA  SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)  Continued From page 8 Kitchen,  b.) One (1) corroded sprinkler head in the waik in refrigerator, c.) One (1) corroded sprinkler head in the Laundry, d.) One (1) painted sprinkler head in the 400 Hallway Shower Room. e.) One (1) painted sprinkler head in the 500 Hallway Soiled Linen Room.  Interview of the Maintenance Director revealed he was not aware of the deficiencies prior to the date of the survey.  Actual NFPA standard:  NFPA 25  5.2.1.1* Sprinklers shall be inspected from the floor level annually.  5.2.1.1.1 Sprinklers shall not show signs of leakage; shall be free of corrosion, foreign materials, paint, and physical damage; and shall be installed in the correct orientation (e.g., upright, pendent, or sidewall).  5.2.1.1.2 Any sprinkler that shows signs of any of the following shall be replaced: (1) Leakage (2) Corrosion (3) Physical damage (4) Loss of fluid in the glass bulb heat responsive element (5)*Loeding (6) Painting unless painted by the sprinkler	PROMDER OR SUPPLIER  IRING HEALTH & REHABILITATION OF CASCADIA  SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST' SE PRECEDED BY PULL REGULATORY OR LSC IDENTIFYING INFORMATION)  Continued From page 8  Kitchen,  b.) One (1) corroded sprinkler head in the walk in refrigerator,  c.) One (1) corroded sprinkler head in the 400 Hailway Shower Room.  e.) One (1) painted sprinkler head in the 500 Hailway Soiled Linen Room.  Interview of the Maintenance Director revealed he was not aware of the deficiencies prior to the date of the survey.  Actual NFPA standard:  NFPA 26  5.2.1.1* Sprinklers shall be inspected from the floor level annually.  5.2.1.1.1* Sprinklers shall not show signs of leakage; shall be free of corrosion, foreign materials, paint, and physical damage; and shall be installed in the correct orientation (e.g., upright, pendent, or sidewall).  5.2.1.2 Any sprinkler that shows signs of any of the following shall be replaced:  (1) Leakage (2) Corrosion (3) Physical damage (4) Loss of fluid in the glass bulb heat responsive element (5)*Loeding (6) Painting unless painted by the sprinkler	PROVIDER OR SUPPLIER  135094  PROVIDER OR SUPPLIER  RING HEALTH & REHABILITATION OF CASCADIA  SUMMARY STATEMENT OF DEFICIENCIES (SACH DESIGNERY MILES THE PRECEDED BY PLUL, RESULATORY OF LEST DEPINIFIED HAND AND ALL DESIGNERY MILES THE PRECEDED BY PLUL, RESULATORY OF LEST DEPINIFIED HAND AND ALL DESIGNERY MILES THE PRECEDED BY PLUL, RESULATORY OF LEST DEPINIFIED HAND AND ALL DESIGNERY MILES THE PRECEDED BY PLUL, RESULATORY OF LEST DEPINIFIED HAND AND ALL DESIGNERY PLAN OF CORRECTIVE ACTION OF BEHAVIOR AND ALL DESIGNERY PLAN OF CORRECTIVE ACTION OF BEHAVIOR AND ALL DESIGNERY PLAN OF CORRECTIVE ACTION OF BEHAVIOR AND ALL DESIGNERY PLAN OF CORRECTIVE ACTION OF BEHAVIOR OF A PROPORTION OF A PROPORT		

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES
STATEMENT OF DEPOISORIES
(X1) PROVIDER/SUPPLIER/CLIA

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER.			LTIPLE CONSTRUCTION DING 01 - ENTIRE BUILDING	(X3) DATE SURVEY COMPLETED	
		135094	B WING	3	05/10/2017
	PROVIDER OR SUPPLIER PRING HEALTH & RE	HABILITATION OF CASCADIA		STREET ADDRESS, CITY, STATE, ZIF 2106 12TH AVENUE ROAD NAMPA, ID 83686	CODE
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	PREF TAG		ON SHOULD BE COMPLETION PATE DATE
SS#E	Draperies, Curtain Draperies, curtains loosely hanging far accordance with 1 draperies: at show patient sleeping rocompartments; en in sprinklered compartments; en in sprinklered or the wall 18.7.5.1, 18.3.5.11 This STANDARD Based on record interview, the facility resistive properties Fallure to provide ensure the flame in hanging curtains of spread of fire durity practice affected 3 on the date of the for 120 SNF/NF be the day of the survival of the survival of the survival of the for 120 SNF/NF be the day of the survival of the surviv	, 19.7.5.1, 19.3.5.11, 10.3.1 is not met as evidenced by; eview, observation and ty falled to ensure the flame as of loosely hanging curtains. flame spread ratings and esistive properties of loosely ould add to the growth and ag a fire event. This deficient is residents, staff and visitors survey. The facility is licensed add and had a census of 59 on		761  K751- Drapes/Curtains  Maintenance Director Theater room, carpet-l in main hall, with certif retardant June 1, 2017  Maintenance Director Identity other textiles of cellings requiring treat each case individually.  Maintenance Director completion of treatme audit facility for like m manufacturer guidelin	sprayed curtains in like wall treatments fied Flame  will audit facility to on walls and ment and treat  will document ents, and routinely aterials. Per es, maintenance eatments annually, Inc. 1
	revealed the curta labeling to indicate Upon further calcu	. Further physical observation ins to be fabric yardage, without a flammability rating.  Illustrian of the Theatre Room alos exceeded 20 percent of the			

PRINTED: 05/18/2017

DEPARTMENT OF HEALTH AND HUMAN SERVICES FORM APPROVED CENTERS FOR MEDICARE & MEDICAID SERVICES OMB NO. 0938-0391 Statement of deficiencies and plan of correction (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY IDENTIFICATION NUMBER COMPLETED A BUILDING 01 - ENTIRE BUILDING 138094 B WING 06/10/2017 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 2105 12TH AVENUE ROAD WELLSPRING HEALTH & REHABILITATION OF CASCADIA NAMPA, ID 83886 SUMMARY STATEMENT OF DEFICIENCIES (X4) ID PREFIX PROVIDER'S PLAN OF CORRECTION (X\$) COMPLETION DATE (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX EACH CORRECTIVE ACTION SHOULD BE REGULATORY OR LSC (DENTIFYING INFORMATION) TAG TAG CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY) K 751 Continued From page 10 K 761 aggregate area of the wall on which they were located. When asked if the facility had applied any type of .. flame retardant to the curtains, the Maintenance Director stated he was not aware of апу. Actual NFPA standard: : NFPA 101 19.7.8.1\* Draperies, curtains, and other loosely hanging fabrics and films serving as furnishings or decorations in health care occupancies shall be in accordance with the provisions of 10.3.1 (see 19.3.5.11), and the following also shall apply: (1) Such curtains shall include cubicle curtains, (2) Such curtains shall not include curtains at showers and baths. (3) Such draperies and curtains shall not include draperies and curtains at windows in patient sleeping rooms in smoke compartments sprinklered in accordance with 19.3.5. (4) Such draperies and curtains shall not include : draperies and curtains in other rooms or areas where the draperies and curtains comply with all of the following: (a) Individual drapery or curtain panel area does not exceed 48 ft2 (4.5 m2). (b) Total area of drapery and curtain panels per room or area does not exceed 20 percent of the aggregate area of the wall on which they are located. (c) Smoke compartment in which draperies or ' curtains are located is sprinklered in accordance with 19.3.5 10.3 Contents and Furnishings. 10.3.1" Where required by the applicable

	OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A BUILDING 01 - ENTIRE BUILDING		(X3) DATE SURVEY COMPLETED
		135094	B WING	The statement of the st	05/10/2017
	Provider or supplie RING HEALTH & RI	r Ehabilitation of Cascadia	2	ntreet address, city, state, zip code 1995 12TH Avenue Road Nampa, ID 83686	
(X4) ID PREFIX TAG	(SACH DEFICIÉN	TATEMENT OF PEFICIENCIES CY MUST BE PRECEDED BY FULL LEC (DENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTIVE (EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPRO DEFICIENCY)	HOITEJANOD BB C.
K 927 SS=D	other similar loos decorations shall performance critical Standard Method Propagation of Tensfilling of oxy is in accordance. High Pressure Granditions under conditions under Transfilling to liquid to portable containe conditions under Transfilling to liquid portable containe conditions under 11.5.2.2 (NFPA 9 This STANDARD Based on observations oxygen rich envir for combustion. Tresidents, staff a survey. The facility beds and had a courvey.	Code, draperies, curtains, and ely hanging furnishings and meet the flame propagation or a contained in NFPA 701, as of Fire Tests for Flame extiles and Films, quipment - Transfilling Cylinders  Transfilling Cylinders gen from one cylinder to another with CGA P-2.5, Transfilling of asseous Oxygen Used for assilling of any ges from one or is prohibited in patient careing to liquid oxygen containers or iners over 50 psi comply with 11.5.2.3.1 (NFPA 99), and oxygen containers or to use under 50 psi comply with 11.6.2.3.2 (NFPA 99).  Is not met as evidenced by: vetton and operational testing, to ensure liquid oxygen conducted in accordance with to transfill liquid oxygen with lation could result in creating a comment, increasing the potential finis deficient practice affected 19 nd visitors on the date of the ty is licensed for 120 SNF/NF beansus of 59 on the day of the	K 751	K 927- Gas Filling Equipment Maintenance Director repaired exygen transfill area on May 12 are no other oxygen filling trans Oxygen fill area doors will be ch quarterly for circulatory functio reported at the facilities Annual meeting.	, There fill areas ecked n and
	During the facility from approximat	y tour canducted on May 9, 2017 ely 1:00 PM to 4:30 PM,	·		,

PRINTED: 05/18/2017 DEPARTMENT OF HEALTH AND HUMAN SERVICES FORM APPROVED CENTERS FOR MEDICARE & MEDICAID SERVICES OMB NO. 0938-0391 STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY COMPLETED AND PLAN OF CORRECTION DENTIFICATION NUMBER A BUILDING 01 - ENTIRE BUILDING 135094 8. WING 05/10/2017 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 2106 12TH AVENUE ROAD WELLSPRING HEALTH & REHABILITATION OF CASCADIA NAMPA, ID 83686 SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) PROVIDER'S PLAN OF CORRECTION (X4) ID (X5) COMPLETION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE PREFIX PREFIX DATE TAG TAG DEFICIENCY) K 927 Continued From page 12 K 927 observation and operational testing of the fan for the oxygen storage/transfill area revealed the fan was not operational. Actual NFPA standard: NFPA 99 11,5.2,3 Transfilling Liquid Oxygen, Transfilling of Ilquid oxygen shall comply with 11.5.2.3.1 or 11.5.2.3.2, as applicable. 11.5.2.3.1 Transfilling to liquid oxygen base reservoir containers or to ilquid oxygen portable containers over 344,74 kPa (50 psi) shall include the following: (1) A designated area separated from any portion of a facility wherein patients are housed. examined, or treated by a fire barrier of 1 hour fire-resistive construction. (2) The area is mechanically ventilated, is sprinklered, and has ceramic or concrete flooring. (3) The area is posted with signs indicating that transfilling is occurring and that smoking in the immediate area is not permitted. (4) The individual transfilling the container(s) has been properly trained in the transfilling procedures. 9.3.7.5.3.2 Mechanical exhaust shall be at a rate : of 1 L/sec of sirflow for each 300 L (1 cfm per 5 ft3 of fluid) designed to be stored in the space and not less than 24 L/sec (50 cfm) nor more then 235 L/sec (500 cfm).